

PF Cusack Garment Care

Garment Care

Please refer to these tables and find the label inside each garment showing the appropriate care instructions.

This will allow you to care for your garments and increase their life cycle and prolong their protection.



	Cotton Wash (no bar underneath image) Maximum wash - the number within the washtub is the maximum wash temperature.
	Synthetics Wash / mild treatment (single bar) Medium wash (mild washing conditions).
	Wool Wash / very mild treatment (double bar) Minimum wash (delicate washing conditions).
	Hand Wash Only Do not machine wash. Wash by hand, maximum temperature 40°C, handle with care.
	Not suitable for washing

	May be tumble dried
	Tumble dry low (low heat setting)
	Tumble dry high (high heat setting)
	Do not tumble dry

	Dry flat Recommended for garments which are easily distorted by vertical drying.
	Hang / Line dry For garments not distorted by vertical drying or where tumble drying is not recommended.
	Drip dry Recommended for garments which withstand distortion - generally synthetic in nature.

	Cool iron (one dot) Maximum sole-plate temperature of 110°C, steam - ironing may be a risk.
	Warm iron (two dots) Maximum sole-plate temperature of 150°C
	Hot iron (three dots) Maximum sole-plate temperature of 200°C
	Do not iron Steaming and steam treatments are not allowed.

	Any bleach allowed Chlorine based bleaching allowed, only cold and dilute solution
	Only oxygen bleach/non-chlorine bleach allowed
	Do not bleach

	May be dry cleaned
	May be dry cleaned (this letter tells the dry cleaner what process is required)
	Do not dry clean or remove stains with solvents